







Thermoplastic sheet build up (exploded view)




Difference between total thickness (yellow arrow) and thickness above scrim (orange lines)





Colour Testing Sample Range



SinglePly heat test		12/03/2021 Nuralite, 60D Leon Leicester Avenue, Auckland				
Time	Ambient air temp	Membrane A	Membrane B	Membrane C	Membrane D	Membrane E Notes
9.00 AM	18.0 C°	28.2 C°	34.1 C°	47.6 C°	45.0 C°	49.8 C°
10.00 AM	18.0 C°	30.6 C°	42.4 C°	60.8 C°	56.4 C°	61.8 C°
11.00 AM	18.0 C°	40.6 C°	53.7 C°	75.7 C°	70.6 C°	71.5 C°
12.00 PM	19.0 C°	40.6 C°	54.7 C°	78.6 C°	71.3 C°	74.8 C°
1.00 PM	21.0 C°	48.8 C°	62.2 C°	87.3 C°	81.8 C°	87.5 C°
1.30 PM*	22.0 C°	46.8 C°	62.3 C°	94.2 C°	86.7 C°	99.6 C° *solar noon
2.00 PM	23.0 C°	47.1 C°	62.2 C°	91.6 C°	86.4 C°	96.6 C°
2.30 PM	24.0 C°	47.3 C°	63.1 C°	93.1 C°	84.4 C°	95.7 C°

